UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

: 6,929,781 B1

Page 1 of 1

DATED

: August 16, 2005

INVENTOR(S) : Michael Hohmann et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3,

Line 51, reads "connections 10" should read -- connections (10) --.

Line 66, reads "fluid line 10b" should read -- fluid line (10b) --.

Line 67, reads "hole 10" should read -- hole (10) --.

Column 4,

Line 44, reads "plane parallel" should read -- plane-parallel --.

Line 60, reads "has a substantially" should read -- has substantially --.

Column 5,

Line 8, reads "hole 10" should read -- hole (10) --.

Line 11, reads "connection 11" should read -- connection (11) --.

Line 23, reads "side wall 9" should read -- side wall (9) --.

Signed and Sealed this

Twenty-first Day of March, 2006

JON W. DUDAS
Director of the United States Patent and Trademark Office